

Is Restricted Flow Costing You Money?

If your suction outlet cover has a low open surface area, you may be pouring money down the drain. Covers with small open surface areas result in reduced circulation pump efficiencies. These hydraulically inefficient covers not only cost you more money to circulate the water in your pool, but due to higher cover velocities they can increase the risk for bather injury. *We can fix your problem.*



The DS 360 M offers:

- **Hydraulically efficient 27 sq. in. open surface area**
- **Lower cover velocities for increased bather safety**
- **Certified Safe Flow of 123 G.P.M. @ 1.5 F.P.S.**
- **Easy installation on a vertical or horizontal plane**

**For more details call 800-513-4372
or visit www.Drainsafe.com**